

Porter Pollock Estate:
Caretaker's Residence
603 Wick Avenue
Youngstown
Mahoning County
Ohio

HABS No. OH-2329

11/25

OHIO.

ED-YOUNG

6-

PHOTOGRAPHS


WRITTEN HISTORICAL AND DESCRIPTIVE DATA


HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

HABS
OH-10,
50-Young
6-

ARCHITECTURAL DATA FORM

STATE Ohio	COUNTY Mahoning	TOWN OR VICINITY Youngstown
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Porter Pollock Estate, Caretaker's Residence		HABS NO. OH- 2329
SECONDARY OR COMMON NAMES OF STRUCTURE Residence Head Groundskeeper's House Youngstown State University		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 603 Wick Avenue Youngstown, Ohio City Lots #11394 and #11395		
DATE OF CONSTRUCTION (INCLUDE SOURCE) C. 1907 - 1929 "Sanborn Maps" Mahoning Valley Historical Society		ARCHITECT(S) (INCLUDE SOURCE) Not Known
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Building is a residence on the Porter Pollock Estate which is located in the Wick Avenue Historical District (National Register). Residence was first used to house the caretaker's family.		
STYLE (IF APPROPRIATE)		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Standard wood stud & joist construction, basement has concrete floor, foundation walls are glazed clay block and concrete; asphalt shingle roof; wood windows and doors.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) (See Attached Floor Plans) 23'-1" x 28'-5" House 7'-6" x 21'-6" Porch on SW corner		
EXTERIOR FEATURES OF NOTE Exterior is sheathed with wood shake shingles. Gable rakes are trimmed with flat boards and a modest cornice moulding. Trim around windows and doors is flat boards.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) (See Attached Floor Plans) Interior woodwork is painted flat stock, floors in living room, dining room and bedrooms are T&G oak, asphalt tile floors in bath and kitchen. Ornate cast iron wall registers on first floor.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES None		
PRESENT CONDITION AND USE Vacant Plumbing, mechanical and electrical systems are not in working order. Exterior is in need of major woodwork repair, interior needs to be refurbished.		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) 1974 - Wick Avenue Historic District - National Register "Sanborn Maps" - Mahoning Valley Historical Society		
COMPILER, AFFILIATION Gary G. Balog, AIA BUCHANAN, RICCIUTI & ASSOCIATES, INC. ARCHITECTS		DATE 5/3/88







BASEMENT

scale: $\frac{1}{8}$ inch = 1 foot

4.15.08






FIRST FLOOR

Scale: $\frac{1}{8}$ inch = 1 foot

4.15.88





SECOND FLOOR

Scale: $\frac{1}{8}$ inch = 1 foot

4.15.88

